






## PARTS LIST


	DESCRIPTION	QTY	SIZE (L x W)	
<b>A</b>	MOUNTING PLATE	1	12" X 12"	
<b>B</b>	COLUMN	1	VARIABLES: 26 3/16" STANDARD HEIGHT 38 1/8" BAR HEIGHT	
<b>C</b>	BASE	1	VARIABLES: 22" 28" 30" 35"	

## HARDWARE PARTS LIST

	DESCRIPTION	QTY	SIZE (L x W)	
<b>1</b>	FLAT HEAD SCREW	6	1 1/4" X 1/4"	
<b>2</b>	LEVELER	3	1" X 1"	

## TOOLS NEEDED

PHILLIPS SCREWDRIVER



SAFETY GLASSES




## DIRECTIONS


- CHECK ALL PARTS PRIOR TO ASSEMBLY FOR PROPER QUANTITIES.
- INSPECT CONDITION OF ALL PARTS.
- CAREFULLY FOLLOW ATTACHED "ASSEMBLY DIAGRAM".
- SPECIAL NOTES/DETAILS WILL BE ILLUSTRATED OR EXPLAINED.

IF ANY ITEMS ARE FOUND TO BE MISSING OR DAMAGED, PLEASE CONTACT YOUR SALES REPRESENTATIVE FROM WHICH IT WAS PURCHASED OR NIULINE AT (602) 861-2828.

## ASSEMBLY DIAGRAM




- ① 3 FLAT HEAD SCREWS SCREW THROUGH TOP PLATE IN 3 HOLES THAT FORM A “TRIANGLE” AND INTO THE COLUMN. MAKE SURE SCREWS ARE FLUSH.




- ? CUSTOMER TO USE OWN SCREWS WHEN MOUNTING BASE UNDER TABLE TOP.

***SCREWS NOT PROVIDED BY NIULINE***



- ② SCREW 3 LEVELERS INTO INSERT SLOTS ON BOTTOM OF BASE.

REPEAT FOR ALL LEVELERS.  
ADJUST AS NECESSARY.



- ① 3 FLAT HEAD SCREWS SCREW THROUGH BASE INTO THE COLUMN. MAKE SURE SCREWS ARE FLUSH.

