













FRAME PARTS LIST

PART		QUANTITY
A	SIDE FRAMES 	2
B	BACK SUPPORT 	1
C	LEG REST 	1
D	ARM REST 	1
E	SEAT 	1
F	FOOT REST 	1


PART		QUANTITY
G	BELT + BUCKLE 	1
H	LEG SUPPORT BELT 	1
1	WOOD PIN 	6
2	HEX SCREW 	14
3	WOOD SCREW 	6

TOOLS NEEDED

6MM HEX SCREWDRIVER




RUBBER Mallet



SAFETY GLASSES



POWER DRILL





DIRECTIONS

- CHECK ALL PARTS PRIOR TO ASSEMBLY FOR PROPER QUANTITIES
- INSPECT CONDITION OF ALL PARTS
- CAREFULLY FOLLOW ATTACHED "ASSEMBLY DIAGRAM". SPECIAL NOTES/ DETAILS WILL BE ILLUSTRATED OR EXPLAINED.

IF ANY ITEMS ARE FOUND TO BE MISSING OR DAMAGED, PLEASE CONTACT YOUR SALES REPRESENTATIVE FROM WHICH IT WAS PURCHASED OR NIULINE AT (602) 861-2828.

ASSEMBLY DIAGRAMS

○ SLIDE HANDLE BAR THROUGH THE OPENING OF THE LEG SUPPORT BELT.



- ① AFFIX WOOD PINS BEFORE TIGHTENING HEX SCREWS.
- ② SCREW HEX SCREWS INTO DESIGNATED AREAS.

③ PLACE ENDS OF BELT UNDER THE SEAT AND SCREW INTO THE BOTTOM OF THE SEAT WITH POWER DRILL.

